









- The Naval Aviation Depot is an industrial facility within the NAVAIR corporation
- "Depot" level rework is performed on aircraft, engines and components





_	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec
195	Start Impl.				EV Training					enem (cc.		System Rqmts.
.96	System Rqm	ts.		, de a liga a de la liga a de l			11,000 a				liness ⁄iew	
.97	Validati Revie	THE RESERVE OF THE PARTY OF THE	/stem eptance	Relativity						i i i i i i i i i i i i i i i i i i i		
.98	Re-Des Decis	HID O. A. S. HARRIS LINES BY L. D. C.					B	Integra aseline		in the s		Critical Design Review
199					Charles and the Control of the Contr	-House Worksh	CONTRACTOR OF THE A			####, 0€ ## #################################		MRPII Integration





Building Blocks Blocks

Changed Org. Culture

Reliable Data

Appropriate Work Breakdown Structure

Responsible Control Account Managers


Realistic Critical Path Model

Early Management Buy-In






- Early Management Buy-In
 - Understanding. . .
 - what EV is and the benefits
 - the process and resource requirements
 - customer requirements
 - the integration with other management initiatives













tailored to reflect

project constraints

- Realistic Critical Path Model
 - Measurable activities which relate to the work to be accomplished Template model
 - Production input
 - Relationships drive the schedule



















• Responsible Control Account Managers








- Appropriate Work Breakdown Structure
 - Must relate to production-based activities







Meaningful **Variance Analysis**








• Reliable Data

- Centralized EV data
- Defined interfaces


- Timeliness required to








- Changed Organizational Culture
 - Accepted management tool
 - Production floor buy-in
 - CPM Model
 - Variance Analysis at a meaningful level







- Evolving process
 - Fear of the unknown
 - Adapting to personal management styles
 - Business Process Re-Engineering
 - Resource assignment
 - Team establishment








Changed Org. Culture

Reliable **Data**



Appropriate Work Breakdown Structure

Responsible Control Account Managers

Realistic Critical Path Model

Early Management Buy-In

